## **EAST Search History**

| Ref<br># | Hits   | Search Query  | DBs  | Default<br>Operator | Plurals | Time Stamp       |
|----------|--------|---|--|---------------------|---------|------------------|
| L1       | 288548 | (screw nut bolt fastener ).clm.                                 | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:19 |
| L2       | 87997  | 1 and (force load strain stress pressure ).clm.                 | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:48 |
| L3       | 852    | 2 and (piezo\$9).clm.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:17 |
| L4       | 43     | 3 and (washer ).clm.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:09 |
| L5       | 41     | 4 and (measur\$4 sens\$4 detect\$4 transducer gage gauge )      | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:19 |
| L6       | 2      | 5 and (electrical\$4) near3 (resistance resistiv\$4)            | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:19 |
| L7       | 14054  | 2 and (measur\$4 sens\$4 detect\$4 transducer gage gauge ).clm. | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | ON      | 2007/08/13 18:16 |

## **EAST Search History**

| L8  | 499 | 7 and (electrical\$4) near3 (resistance resistiv\$4)        | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:17 |
|-----|-----|---|--|----|----|------------------|
| L9  | 150 | 7 and (electrical\$4) near3 (resistance resistiv\$4 ).clm.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:17 |
| L10 | 34  | 9 and (piezo\$9)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:18 |
| L11 | 580 | 73/761.ccls.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:19 |
| L12 | 451 | 11 and (screw nut bolt fastener )                           | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:48 |
| L13 | 401 | 12 and (force load strain stress pressure )                 | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:19 |
| L14 | 376 | 13 and (measur\$4 sens\$4 detect\$4 transducer gage gauge ) | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:19 |

8/13/07 7:18:02 PM Page 2

## **EAST Search History**

|     |       |  | ,  |    |    |                  |
|-----|-------|--|--|----|----|------------------|
| L15 | 17    | 14 and (electrical\$4) near3 (resistance resistiv\$4)              | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:47 |
| L16 | 11265 | (chang\$4) near3 (electrical\$4) near3<br>(resistance resistiv\$4) | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:47 |
| L17 | 1989  | 16 and (screw nut bolt fastener )                                  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:48 |
| L18 | 304   | 17 and (washer)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:48 |
| L19 | 74    | 18 and (piezo\$9)  | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 18:48 |
| L20 | 73    | 19 and (force load strain stress pressure )                        | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 19:15 |
| L21 | 6     | 20 and (amorphous)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>FPRS;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2007/08/13 19:15 |

8/13/07 7:18:02 PM Page 3